



Coal
JSAC 0521

ppm

	As	B	Be	Cd	Co	Cr	Cu	F
농도	19.7	148	3.03	0.46	27.8	102	103	153
허용오차	1.3	10	0.31	0.31	4.1	4	4	7
	Hg	Mn	Ni	Pb	Se	V	Zn	
농도	0.14	315	62.8	54	0.75	225	137	
허용오차	0.01	11	2	4.4	0.1	6	8	

Coal
JSAC 0522

ppm

	As	B	Be	Cd	Co	Cr	Cu	F
농도	55.2	85.6	10.4	0.98	47.4	139	113	33
허용오차	3.5	6.7	0.7	0.13	6.2	5	5	13
	Mn	Ni	Pb	V	Zn			
농도	240	106	98.1	130	303			
허용오차	8	5	5.8	7	19			

Coal Fly Ashes
SRM2689

3 glass vials each 10g

ppm

	Al	Ca	Fe	K	Mg	Na	P	Si
농도	12.94	2.18	9.32	2.2	0.61	0.25	0.1	24.06
허용오차	0.21	0.06	0.06	0.03	0.05	0.03	0.01	0.08
	Ti							
농도	0.75							
허용오차	0.01							

Coal Fly Ashes
SRM2690

3 glass vials each 10g

ppm

	Al	Ca	Fe	K	Mg	Na	P	Si
농도	12.35	5.71	3.57	1.04	1.53	0.24	0.52	25.85
허용오차	0.28	0.13	0.06	0.04	0.05	0.02	0.01	0.17
	Ti							
농도	0.52							
허용오차	0.01							



Coal Fly Ashes

SRM2691

3 glass vials each 10g

ppm

	Al	Ca	Fe	K	Mg	Na	P	Si
농도	9.81	18.45	4.42	0.34	3.12	1.09	0.51	16.83
허용오차	0.39	0.32	0.03	0.01	0.08	0.05	0.02	0.12
	Ti							
농도	0.9							
허용오차	0.02							